




16 - Thickness (in feet) of Sandstone overlying D.F. coal

 Areas of "bad roof"

 - Locations of mic inspector sample points. Size of circle indicates uncertainty of location.

 Lines of cross-section

AS
Oct. 1975