



D.D.H. #4
 ELEV. SURFACE 1139.2
 ELEV. BOT. HOLE 1074.2
 (1928)

D.D.H. #3
 ELEV. SURFACE 1113.5
 ELEV. BOT. CLAY 1072.5
 (1928)

D.D.H. #2
 ELEV. SURFACE 1117.2
 ELEV. BOT. CLAY 1047.2
 (1928)

D.D.H. #5
 ELEV. SURFACE 1152.6
 ELEV. BOT. HOLE 1052.6
 (1928)

D.D.H. #1
 ELEV. SURFACE 1117.5
 ELEV. BOT. CLAY 1031.0
 (1928)

D.D.H. #10
 ELEV. SURFACE 1080.2
 ELEV. BOT. CLAY 1031.5
 (1928)

D.D.H. #6
 ELEV. SURFACE 1164.6
 ELEV. BOT. HOLE 1049.6
 (1928)

D.D.H. #7
 ELEV. SURFACE 1138.8
 ELEV. BOT. HOLE 1013.8
 (1928)

D.D.H. #9
 ELEV. SURFACE 1078.5
 ELEV. BOT. HOLE 993.5
 (1928)

D.D.H. #8
 ELEV. SURFACE 1061.1
 ELEV. BOT. CLAY 990.1
 (1928)

CRESCENT REFRACTORIES CO.
 CURWENSVILLE, CLEARFIELD COUNTY, PA.
 ENGINEERING DEPARTMENT

MAP SHOWING THE LOCATION OF
 DIAMOND DRILL HOLES ON THE
 PROPERTY OF MABEL BLOOM ET AL.

NOTE:-
 LEVELS FROM DATUM AT
 IRVIN & MURRAY MINE.
 TO REDUCE TO U.S.G.S. ADD 760 FT.

DRAWN <i>R.H.</i>	SCALE 1" = 200 FT.	50-3-162
CHECKED	DATE July 19 th 1928	1088-I
REFERENCE	ORDER	