



- VENTILATION SYMBOLS**
- (F) = Main Fan
 - (A) = Auxiliary Fan
 - = Air Flow - Intake
 - ⇝ = Air Flow - Exhaust
 - |— = Permanent Stopping
 - - -| - - - = Temporary Stopping
 - ⊠ = Air Bridge
 - R = Regulator
 - ∇ = Man Door
 - V = Velocity, fpm
 - Q = Quantity, cfm
 - WG = Water Gauge
 - (E) = Escapeway
 - BEP = Bleeder Evaluation Point

MINE MAP

Showing the location and extent of development of the Shadle Coal Company mine. Situate on the south dip (inverted) Primrose vein, Tremont Township, Schuylkill County.

J. Riedel, P.E. Jan. 21, 1992 Scale 1"=100'

Alfred B. Riedel