



BILL OF MATERIAL				
MARK	NO. REQ.	MAT'L.	DESCRIPTION	REMARKS
A	2	STEEL	8" W ⁶ BEAM x 6 1/2" @ 24" x 12' 4" LG.	
B	4	"	8" C @ 13.75# x 12' 4" LG.	
C	2	"	1 5/8 3" x 3" 1/4" x 7' 4"	
D	73	"	Sq. Ft. 1/4" CHECKERED FLOOR PLT.	
E	2	"	LIFT RINGS WITH EYE BOLTS	
F	1	"	SET OF HINGES, 5 LG. LEAVES,	6 3/4" LEAVES.
G	1	"	1" DIA. x 7' 6 3/8" HINGE PIN	
H	2	"	6" x 3/8" x 7" BEARING PLATES	
J	4	"	3 x 3/8 x 6 " "	
K	1	"	8" SHIP C @ 19.3# x 16' 7" LG.	
L	18	"	5/8" x 6" LG BOLTS WITH EXPANSION SLEEVES	
M	2	"	8" C @ 13.75# x 19' 0" LG.	GUIDES
N	4	"	1 5/8 4" x 3" x 3/8" x 10' 0" "	SUPPORTS
P	10	"	L 5/8 3 1/2 x 3 1/2 x 3/8" 0' 8" "	CLIPS
Q	4	"	1 5/8 3" x 3" x 1/4" x 7' 0" "	BRACES
R	2	"	1 5/8 3 x 3 x 1/4 x 7' 0" "	"
S	2	"	GUSSETS 6" x 1/4" x 24" PL.	
T	1	Q315/ARM	COUNTERWEIGHT 3' 0" x 2' 1/2" x 6"	IN SECTIONS
U	1	STEEL	8" B" COLUMN @ 33# x 22' 6"	OVERALL
V	1	"	10" C @ 20# x 18' 0" LG.	
W	2	"	1 5/8 3" x 3" x 3/8" x 3' 6"	
X	2	"	L 5/8 2 1/2 x 2 1/2 x 3' 6"	KNEE BRACES
Y	2	"	8" C @ 13.75# x 2' 7 1/2"	MOTOR SUPPS.
Z	1	"	15" x 3/8" x 19" PL.	MOTOR BASE
ZZ	1	"	6" x 3/8" x 9 1/4" PL.	
YY	1	"	TOP SHAFT ASSEMBLY	
XX	4	"	BEARINGS FOR TOP SHAFT	
VV	1	"	OPERATING SHAFT ASSEMBLY	
WW	4	"	BEARINGS FOR OPERATING SHAFT	
UU	90	"	LIN. FT. 6 x 37 FLEXIBLE CABLE	1/2" DIA.
TT	2	"	HOOKS FOR LIFT CABLES	
SS	7	"	CABLE CLAMPS FOR 1/2" CABLE	
	1	GE	2HP. DRIP PROOF CONCENTRIC MOTOR	FRA# 184" 523
	16	STEEL	MACHINE BOLTS 3/4" x 2 1/2"	LOCK WASHERS
	4	"	" " 5/8" x 2 1/2"	" "

O'DONNELL NO. 1. MINE
WORKING PLATFORM
FOR MAN SHAFT.

MADE BY <u>F.P.S.</u>	SCALE <u>1" = 3" = 1'-0"</u>
TRACED BY <u>"</u>	DATE <u>7-3-57</u>
CHECKED BY ☒	NO. <u>(2)</u>