

DDH 1703
"FAULT"

DDH 446
56 3/4"
NO SANDSTONE WITH
IN 30' OF COAL

DDH 126
68"
NO SANDSTONE
WITH IN 30'
OF COAL

DDH 2626
69"
168' SANDSTONE AT
2.3' ABOVE COAL

DDH 2621
67 1/4"
2.3' SANDSTONE AT
26.8' ABOVE COAL

A2 DDH 2616
69"
17.5' SANDSTONE AT
2.1' ABOVE COAL
DDH 1997
57"
15.3' SANDSTONE AT
2.9' ABOVE COAL

DDH 2620
69 1/4"
15.8' SANDSTONE AT
4.0' ABOVE COAL

A3 DDH 2614
75 1/4"
NO SANDSTONE WITHIN
30' ABOVE COAL
DDH 2615
75"
10.7' SANDSTONE AT
1.8' ABOVE COAL

DDH 2123
71 1/4"
11.6' SANDSTONE AT
2.8' ABOVE COAL

A1 DDH 1600
65 1/2"
NO SANDSTONE WITHIN
30' ABOVE COAL

DDH 2126
71 1/2"
2.3' SANDSTONE AT
11.2' ABOVE COAL

URLING 1 ROCK FAULT NORTH MAINS

- LEGEND
- POOR ROOF (WEAK & DRUMMY)
 - HIGHLY FRACTURED SLICKENSIDED ROOF
 - CHANNEL SANDSTONE SLUMP
 - SANDSTONE WITH IN 30' OF COAL
 - CROSS-SECTION SCALE 1"=200'

IMAPS # 17288