
24 BUTT SUMP
SUB STA
NO 32 BUTT
REPORTED PLUGGED
1934
REPORTED PLUGGED
1934
FAULT