Glendale Mine (Kelly)
Cambria No.1 (in Pass to Barnett)
Cambria No.2 (Barnett)
Buffalo Mine (Kelly)
Kelly mined out
Kelly Seam Worked out (rock survey)
Foreman Mine Workings
Mined Out
Steele Mine
End Stripping (Kelly Seam)