MARTINDALE
FIDDLERS GREEN
MILLER SHAFT
LLOYDELL
RUTHFORD
LOVETT
To Johnstown
John Nicholson No 1
John Nicholson No 62
Isaac Brennan
Richard Smith
Philip George
Barnabas
Wm Smith D.D.
B. L. Wharle
Fludo - Mitchell & Palmer
Geoss & Wright
C. A. McGonigle
N. E. Berkey
C. Shartz
Amos Plummer
W. K. Burnett
George M. Reade
Andrew Brookbank
Joshua Riblett
Wm Moore Smith
William Govett
Edward McGlade
G. W. Kerby
Joseph A. Wright
Robert Erwin
McCormick Est.
Beaver Run Land Co.
Cambria Coal & Iron Co.
Thomas Nichols
D. Neff Est.
D. Neff Hrs
J. L. Knepper
Frank Horner
Burke Tr.
Nick Young
Rhoades & Kring
John Graff
Abandoned
Portage No 10
Portage No 9 Pump Sta.
Portage No 6
Portage No 4 Shaft
Portage No 2
Logan No 2
Logan No 4
Logan No 6
Logan No 3
Ruthford Substation Penna. Electric Co.
Penna Electric Co.
Line Removed 1952
Not Operating
1550
RUTHFORD SUB.
600 HP Pump - L4
150 - L4 Night
415 - L-3 Tipple
75 - HP fan L-4
40 - L-3
300 - B.R. Haulage
50 - B.R. fan
750 - Hoist
1800
Will require 3/cutouts at top of hill
Do at Smith's
11/57
ON RUTHFORD Sub
3065 if
ON SMITH CORNERS
1050 HP 3/500 KVA
1625 HP
If connection is made near top of hill at B.B. field take 550 HP off 3065
2515 HP on 1500 KVA
12000
15000
10,500
Normal 350
To Portage
To South Fork