Map of Baldory Mine No 1
Showing Present Workings
On the Grant Showers Farm
Surveyed June 1918 by H.T. Russell

Jno Smith

Jno Smith

Jno Smith

Jno Sherry

Jno Sherry

Worked out
Room pillars stand

Worked out, mostly
Partly caved

Old Hd'g

Present Haulage Road

Main Road

Unworked Territory

Manway

Test hole

Test hole

Guthrie Hrs

8' of cover over coal

11½ A. of Coal with over 8' of cover

Eight ft of Coal 28 to 36 ft