DDH#17 Sur. 1766.86
May 27 1924
FORK
SOUTH
DDH#28 Sur. 1970.38
DDH#27 Sur. 1875.59
OAL CO.
ER TRACT)
MAIN DIP
3RD LEFT
2ND LEFT
1ST LEFT
Drainage Drift
Heading driven in E. Coal
Shaft
P.R.R.
Beaver Branch of
County Road
Logan #4 Air Shaft
water hole
SUMMIT WATER SUPPLY CO.
Logan has right to drive 3 hdgs. through this land for development, not more than 14 wide, with 30' Pillars and cross-cuts every 50 ft.
1ST RIGHT
2ND RIGHT
3R RIGHT
4th RIGHT
MAIN HEADING
1ST LEFT
2ND LEFT
3RD LEFT
4th LEFT
Faulty Coal
MAIN HEADING
1st PARALLEL
Side Track
Dirty Coal
2ND PARALLEL
DDH#5 Sur. 2393.90 E. 2194.00 C. 2120.57
DDH#4 Sur. 2341.02 E. 2196.69
DDH#3 Sur. 2269.69 E. 2195.42