1 North
12" Borehole

No. 6 Shaft

No. 1 Slopes

No. 1 Shaft
8" Borehole
8" Borehole
6" Borehole
4" Borehole
3" Borehole

No. 3 Shaft

1 West 2 Butt 1 Right
16" Borehole

No. 4 Mainline
4" Borehole

North Mains
6" Borehole

5 North
4" Borehole

Emilie No. 2 Pump Station
12" Borehole
12" Borehole
12" Borehole
4" Borehole

No. 2 Shaft

1 Butt 2 East
16" Borehole

No. 2 Slopes

2 West
12" Borehole

2 South
12" Borehole

No. 2 Drifts

2 West
4" Borehole

2 East
4" Borehole

5 West
4" Borehole

South Mains
4" Borehole

PLUMCREEK & SOUTH BEND TWPS.
ARMSTRONG COUNTY

EMILIE No. 1 & 2 MINE
(UPPER FREEPORT COAL SEAM)

1-1-99 Posted to 10/31/99