

Map of NORTHERN COAL FIELD..
W-BARRE DISTRICT #4
 PLAINS TWP, LUZERNE COUNTY.
 Bennett Vein WILKES-BARRE, PA.
 at HUDSON COAL CO.
 Delaware Colly #2 of 2-TRACING..

Dand H. Co. ... 2 of 2 TRACING..
 Coal Dept

Scale 1"=100'
 Oct. 1920

November 1909
 July 20th 1911
 February 25th 1914
 MAY 13th 1913
 FEB 9th 1912
 JAN 31st 1912
 APR 17th 1911
 OCT 16th 1910
 SEP 23rd 1910
 JUN 22nd 1909
 OCT 15th 1908
 JULY 15th 1905
 JUNE 10th 1902
 NOV 12th 1900
 SEP 23rd 1901
 FEB 9th 1902
 MAR 21st 1902
 OCT 11th 1902
 JUNE 8th 1904
 JAN 29th 1905
 NOV 7th 1906
 JAN 27th 1906
 JAN 14th 1906
 MAY 23rd 1906
 MAY 27th 1906
 JAN 20th 1906
 APRIL 20th 1906
 AUG 20th 1906
 JAN 18th 1906
 JAN 27th 1906
 FEB 14th 1906
 JULY 2nd 1906
 AUG 12th 1906
 AUGUST 27th 1906
 NOV 27th 1906
 MAR 21st 1907
 MAR 12th 1907
 APR 1st 1907
 MAY 20th 1907
 MAY 27th 1907
 DEC 21st 1908 G.C.



Mills Borough

MF

FEB 21 1975

MF

FEB 21 1975