SAFETY ZONE
CATLIN
CAREY
HARTFORD
GERMANIA COAL CO
ROSS' CO
ROSS
HARTFORD COAL CO
DAVIS
W. H. COOK
N.J. COAL CO
W. W. COOK
N.J. COAL CO.
W. W. COOK
CHAS PARRISH
D. L. & W.
No 10 TUNNEL
No 10 TUNNEL AIRWAY
No 56 TUNNEL
No 59 TUNNEL
No 45 TUNNEL
No 46 Tunnel
No 5 SLOPE
No 5 TUNNEL
No 40 TUNNEL
Return Airway
No 23 TUNNEL
No 24 TUNNEL
No 25 TUNNEL
No 24 Tunnel East
AIR SHAFT
No. 12 Plane Rope Hole
No. 10 Slope Rope Hole
No. 8 Slope Rope Hole
MAIN
FAULT
OTCP
Stripping
Pillars tinted red to be left intact for protection of Liverpool Houses
Pillars tinted in red purchased by S.S.&W.Co. to remain intact.
D.D.H. No 2010 Surface 634.86 Top Rock 628.78
D.D.H. No 2014 Surface 636.15 Top Rock 612.15
D.D.H. No 2020 Surface 637.53 Top Rock 630.53
No 149 No 6 Slope Rope Hole Surface 630.53
No 151 No 7 Slope Rope Hole 630.46 Surface
No 2169 639.36 Surf 626.36 Top Rock
B.H. 1406 4" drainage
1000 W
9000 W
8000 W
7000 W
6000 S
F 394 No. 2
F 106 No. 7
F 176
F 394 No. 1
F 395
F 110
F 355 A
F 355 B
F 105 No. 5
B 293
B 293-A
B 295
B 295-A
B 296
B 300
F 104-No. 4
B 479 No. 1
Huber Colly
Top Stanton Vein