




READING ANTHRACITE

COMPANY

COMPANY

VENTILATION SYMBOLS

(F) = Main Fan	(B) = Air Bridge
(A) = Auxiliary Fan	(R) = Regulator
(I) = Air Flow - Intake	(M) = Man Door
(E) = Air Flow - Exhaust	(V) = Velocity, fpm
(P) = Permanent Stopping	(Q) = Quantity, cfm
(T) = Temporary Stopping	(WG) = Water Gauge

MINE MAP
Showing the location and extent of development as per operator of the Bush Coal Co. slope mine, Situate on the North Dip Skidmore Vein, Porter Township, Schuylkill County, PA.
A.B. Riedel, P.E.
August 1, 1989
Scale 1" = 100'

A. B. Riedel