




VENTILATION SYMBOLS	
(F) = Main Fan	(AB) = Air Bridge
(A) = Auxiliary Fan	(R) = Regulator
(I) = Air Flow - Intake	(M) = Man Door
(E) = Air Flow - Exhaust	(V) = Velocity, fpm
(P) = Permanent Stopping	(Q) = Quantity, cfm
(T) = Temporary Stopping	(WG) = Water Gauge

MINE MAP
Showing the location and extent of development of the M.A.I.A. Coal Co. Slope Mine, Situate on the So. dip #8 & 89 Veins, Burnsides Section of Coal Twp., Northumberland County, Pa.
A.B. Riedel, P.E. Aug. 5, 1982
Scale 1"=100'