MINE MAP

Showing the location and extent of development of the H.H. & S. Coal Company slope mine. Situate on the south dip (inverted) Primrose vein, Tremont Twp., Schuylkill County.

A.B. Riedel, P.E. June 24, 1991
Scale 1"=100'

VENTILATION SYMBOLS

- (F) = Main Fan
- (A) = Auxiliary Fan
- = Air Flow - Intake
- = Air Flow - Exhaust
- = Permanent Stopping
- = Temporary Stopping
- = Air Bridge
- R = Regulator
- = Man Door
- V = Velocity, fpm
- Q = Quantity, cfm
- WG = Water Gauge
- (E) = Escapeway
- BEP = Bleeder Evaluation Point

Alfred B. Riedel