40' BARRIER PILLAR
50' BARRIER PILLAR
337° 44' E.
N 40° 26' E
2310.6
Iron Rail
ABANDONED WORKINGS FROM FOREMAN MINE
Traced from Blue Print of Map and Surveys by W. A. Silliman, Engr.
FOREMAN-WHITE COAL CO.
E. 1000
N 2000
N 1000
Kelly Seam worked out
From Survey 1902
Barnett Seam
CAMBRIA IRON CO.
STRIPPING "Kelly Seam"
Manway & Airway
J. H. SIMON & SON
BARRIER PILLAR
Approx. A
Fan
Harriet No. 1
R.R. 1533.0 Kelly Seam
SANDY RUN
Side Track
Pump
Water
Water Seepage
Open Cut
to Barnett Seam. Top Coal 1542.6
Electric Power Line
Public Road
Old Drift
Kelly Seam
Top open cut 1659.4
Mined out
Harriet No. 2
Buffalo Mine
JOHN LANGDON EST.
Shop

No. 3 Mine (Kelly Seam)
Operated by: James L. Tenley

HARRIET MINES

OWNED AND OPERATED BY

J. H. SIMON & SON

ON SANDY RUN - BEDFORD COUNTY - PA.

Scale: 1" = 100'

1942

Guy C. Askey - Min. Engr.
Bedford, Pa.

Revised March 1-1958 (For J. L. Tenley)

Note -
Property Lines without Bearings & Distance were taken from Mine map by A. W. Bodine, Min. Engr.