I have carefully examined the mine map and the strata of several drill holes of the Vinton Colliery Mine No. 6, situate in Blacklick and Buffington Townships, Indiana County, Pennsylvania, and to the best of my knowledge and belief, feel that the mining of the coal seam as indicated, will not sufficiently disturb the overlying strata to be hazardous.

Mining Engineer

February 1, 1921

I have examined this mine map, together with strata of several drill holes of the overlying strata, of Driscoll #1 & Mine, Vinton #6 and it is my opinion that the mining of the coal seam, as shown thereon, will not create any abnormal conditions, and the plan is hereby approved for mining.

DRISCOLL MINING COMPANY

CRESSON, PENNSYLVANIA.

MAP TO ACCOMPANY REQUEST FOR AUTHORIZATION TO MINE WITHIN THE SURFACE ZONE ESTABLISHED BY ACT #303 OF THE LEGISLATURE OF 1921.

SHOWING A PART OF THE WORKINGS OF DRISCOLL NO.1 MINE, FORMERLY VINTON NO.5 MINE, UNDER AND NEAR THE NORTH FORK OF BLACKLICK CREEK, WITH THE EXCLUDED PILLARS AND BARS.

SHOWING THE AREA TO BE MINED AND THE PLANNED METHOD OF MINING.

SITUATED IN BLACKLICK TOWNSHIP, CAMBRIA COUNTY AND BUFFINGTON TOWNSHIP, INDIANA COUNTY, PENNSYLVANIA.

TRACED FROM THE VINTON NO.6 200' SCALE TRACING, AMENDED RECORDS TAKEN FROM THE MINE BY VINTON

SCALE 200'

APPROVED

DEPARTMENT OF MINES AND MINERAL INDUSTRIES

Secretary Louis E. Evans 3/9/21

Deputy Secretary

Division Inspector

Mining Engineer

WM. M. KELLY
Deputy
Mine Inspector