SHEET 4 of 10

SH 4

To SH 1

To SH 5

D N BARBOR

MAIL-BAR COAL CO.

HENRY 2nd Main

BARR MINE

Glen Lime (B) No coal

Sandstone Top on (B) coal

1275
1270
1265
1260
1255
1250
1245
1240

Sheet 4 of 10

SH. 4

To SH 5

To SH-5

Sheet 4 of 10

SH. 4

waste