10 | 11

PENNA

COAL

TOP CLARK BED

GRASSY ISLAND

ABANDONMENT AREA #18

APPROVED 11-10-43

SEE M.D. MAPS 521 ALSO 522

top CLARK

PERMIT NO. 165

PERMIT NO. 211

PERMIT NO. 183

PERMIT NO. 184

PERMIT NO. 235

ABANDONMENT AREA #2-13

ABANDONMENT AREA #3-13

ABANDONMENT AREA #4-13

ABANDONMENT AREA #1-38

ABANDONMENT AREA #2-38

ABANDONMENT AREA #3-38

ABANDONMENT AREA #4-38

ABANDONMENT AREA #5-38

ABANDONMENT AREA #6-38

ABANDONMENT AREA #7-38

ABANDONMENT AREA #8-38

ABANDONMENT AREA #9-38

ABANDONMENT AREA #10-38

ABANDONMENT AREA #11-38

ABANDONMENT AREA #12-38

ABANDONMENT AREA #13-38

ABANDONMENT AREA