JOHN DILLON
JOHN MANION
FRANCIS HUBER
PILLARS TO SUPPORT ROAD ARE MARKED THUS:
D.D.H.
'B' SEAM faulty
Ground Surface 1745.6
N.22° 10' E.
DRIFT
D.D.H.
SUR.=1791.1
BOT. C PRIME=1747.8
ISAAC WEAKLAND
NOTE:-
Points marked "o" means that coal is out
" "p" " pillar is still in
1-26-26
Haulage Road
CAVED
ISAAC WEAKLAND
JOHN MANION
MAP OF
COAL PROPERTY
OPERATED BY
HUETHER COAL COMPANY
HASTINGS, PA.
'C' PRIME SEAM — SCALE-1"=100
DAN. FRITZ TRACT
JULY 12, 1921 I.J. Pfeister, Engr.
Spangler, Pa.
OAK RIDGE DRIFT