JACOB BEST
ROBT NORRIS HEIRS.
FAULT
FAULT
FAULT
BORE HOLE 76
N 86 48 E
954
1059
DRAWER 10
DRAWER 10 PLATE 5