



**BLOSSBURG COAL CO.  
MINE MAP**

OF THE  
**FLOWER RUN MINE**

ARNOT PA. FEB 10 1926  
SCALE 1"=100'-0"

SURVEYED BY A. J. NICHOLSON JULY 28-1927  
 " W. W. PRICE Sept. 7, 1931  
 " W. W. PRICE June, 24, 1932  
 " A. J. NICHOLSON OCT. 12, 1933  
 " A. J. NICHOLSON NOV. 5, 1936  
 " A. J. NICHOLSON DEC. 1, 1937  
 " A. J. NICHOLSON MAR. 7, 1939  
 " F. C. KEENE JULY 24, 1940  
 THIS MINE ABANDONED JULY 1940

COAL LEASED TO  
RAYMOND F. GUY & LEON NORMAN