





Position of victim between face and cutting machine



Cutter was sumping machine into right side of the face as shown in position 1. He misjudged the distance to coal, causing the cutter bar to jump striking the rib at 1'-5" and 3'-0" from corner of face and marked X then struck jack (j-1) which was set in place, the jack did not fall down, but forced the machine toward the face coming into position 2 catching the victim, who was at the controller and friction gear, between the machine and room face

Barnes-Tucker Co,  
#15 Mine, Bakerton, Pa.  
Fatal Accident of  
John Stislow  
April 21, 1945



Rib line

Center line of M-9 Aircourse  
scale 1/8"