

# ROBENA MINE

## FIT-TO-PLAN FOR ASSEMBLY OF MINE SHEETS



		578						460	437			372	354	338	323
	595	577	553	529	505	482	459	436	413	391	371	353	337	322	
612	594	576	552	528	504	481	458	435	412	390	370	352	336	321	
			551	527	503	480	457	434	411	389	369	351	335	320	305
			550	526	502	479	456	433	410	388	368	350	334	319	304
			549	525	501	478	455	432	409	387	367	349	333		
			548	524	500	477	454	431	408	386	366	348	332		
				523	499	476	453	430	407	385	365	347	331		
				522	498	475	452	429	406	384	364	346	330		
						474	451	428	405	383	363	345	329		
								427	404	382	362	344	328		
										T.S.					
										381	361	343	327	312	297
											360	342	160	159	107



Sheet 328 Bundy  
 Sheet 332 Bundy  
 Sheet 436 Bundy  
 Sheet 404 Bundy  
 Sheet 535 Kinby

No Hard Copy