

BELT CONVEYOR


NORTH

TO BAIT  
TO TACKLE WIRE

AIR COURSE

ROOM 44

ROOM 48



PENNSYLVANIA DEPARTMENT OF MINES

DRAWN	7-8-41
SKETCH SHOWING LOCATION OF MINING MACHINE, DRILL, TEST LIGHTS, SWITCH AND TOOLS AFTER EXPLOSION IN KENT NO. 12 MINE, ROCHESTER AND FITZBURGH COAL CO. JUNE 30, 1941. J.F.G.	