



Sketch: No scale

The arch under Horner St. 42' in length, constructed on rubble masonry 3' in height from main floor, balance of brick appears in very good condition.

25 sets of 10" x 10" wood beams extending for 108', set on 4' centers have deteriorated. Concrete block between wood beams are in good condition.