




PLANS OF
COAL COLLIERY - CRABBY SHAFT



MADE DRAWING
MINING OPERATIONS
RIVERDALE COAL MINING CO.
MINE NO. 2
South Park, Pa. August 20, 1914
E. J. S. SIMMONS
E. J. S. SIMMONS

LEASING
E. J. S. SIMMONS
S. J. SIMMONS



Scale
1" = 100'
1" = 200'
1" = 300'
1" = 400'
1" = 500'