



- A = OCT. 13, 1917
- B = MAR. 12, 1918
- C = June 4, 1918
- D = FEB. 26, 1920
- E = JAN. 31, 1921

MINES
OF
RUSH COAL CO.
 ROSTRAVER TOWNSHIP, WESTMORELAND
 COUNTY, PA.
 SCALE - 1" = 100'
 MINE WORKED OUT - JAN. 31, 1921.

OCT. 13, 1917
 S.M. FOUST, C.M.E.
 J.E.H.
 J.E. Hoerstel, C.E.

M-8.