



J. REED

LEVI REED

1-6-37
MAKE SPECIAL EFFORT
TO GET ALL AVAILABLE
COAL BELOW R.R. HDG.
WORKED OUT.

NOTE: 1-1-36 - WORKINGS IN RELATION TO PROJECTIONS:
WORKINGS MUST BE KEPT \geq MINIMUM D.S. FROM R.O.F.W.

1-13-36 - WATER (12-19-36)
When water is released
Places to be surveyed.

DO NOT DRIVE PLACES WITHOUT SIGHTS
WORKINGS NEXT TO RAILROAD MUST BE SURVEYED.

NO 2 MINE
ABANDONED
COMPLETELY UNDER WATER - JUNE 21, 1940