



**LEGEND**

<b>NPDES DISCHARGE POINTS</b>	
001 AMD Plant Discharge	To Be Stopped
002 No. 1 Shaft Discharge	Stopped
003 No. 2 Shaft Discharge	Stopped
004 No. 4 Shaft Discharge	To Be Stopped
005 No. 5 Shaft Discharge	Stopped
006 No. 2 Shaft Sewage Treatment Discharge	Stopped
007 Tipple Runoff No. 1 - Not Shown	To Be Stopped
008 Tipple Runoff No. 2 - Not Shown	To Be Stopped
009 Refine Pile Treated Discharge	To Continue
010 No. 6 Shaft Discharge	To Be Stopped
011 No. 6 Shaft Site Runoff	To Be Stopped
001 No. 6 Shaft Sewage Treatment Plant	To Be Stopped
<b>SURFACE WATER MONITORING POINTS</b>	
A. Upstream A.M.D. Plant Discharge	
B. Downstream A.M.D. Plant Discharge	
C. Downstream Slope Area Runoff	
D. Downstream No. 5 Shaft Discharge	
<b>GROUNDWATER MONITORING POINT</b>	
1. Monitoring Well No. 1	
2. Monitoring Well No. 2	
<b>MINE OPENING</b>	
<b>PERMIT BOUNDARY</b>	



I, the undersigned, hereby certify that this map is correct and shows all the information, to the best of my knowledge and belief, required by the mining laws of this state, and covers the period ending \_\_\_\_\_

THE HELEN MINING COMPANY  
 HOMER CITY MINE  
 Blacklick, Center, Burrell, Conemaugh Townships  
 Indiana County

Upper Freeport "B" Coal Seam Scale 1" = 400'  
 Map Posted to January 31, 1993  
 FINAL MINE MAP  
 WEST SIDE OFFICE COPY

was of  
 was in  
 that shown!  
 see 3750823