



OF
DOUBLE
TIMBER




Method No. 2

Detail showing method of framing
timber at Wanamie Colliery (No. 19)
Experience has indicated this
method to be as good as Method No. 1




Result of Bad Set Under Pressure




Good Set

Method No. 1



Detail showing a
correct method of framing



Bad Set

PROPER METHOD of FRAMING and BLOCKING TIMBER SETS