



VENTILATION SYMBOLS			
(F) = Main Fan	[Square] = Air Bridge	[Star] = Regulator	
(O) = Auxiliary Fan	[Cross] = Man Door		
[Arrow] = Air Flow - Intake			
[Star] = Air Flow - Exhaust			
+ = Permanent Stopping	V = Velocity, fpm		
+ = Temporary Stopping	Q = Quantity, cfm		
	WG = Water Gauge		

MINE MAP
Showing the location and extent of development
of the M.S.W. Coal Company slope mine, situated
on the south dip Lykens Valley #5 and #4 veins,
Foster Township, Schuylkill County, Pa.
A.B. Riedel, P.E.
Feb. 10, 1933
Scale 1"=100'