



VENTILATION SYMBOLS

(F) = Main Fan	▣ = Air Bridge
(O) = Auxiliary Fan	⊥ = Regulator
→ = Air Flow - Intake	⊘ = Man Door
↔ = Air Flow - Exhaust	V = Velocity, fpm
+ = Permanent Stopping	Q = Quantity, cfm
⊕ = Temporary Stopping	WG = Water Gauge

CENTRALIA MINES, INC. MINE MAP
 No. 1 Slope Mine
 36-07835
 Showing the location and extent of development of the Centralia Mines, Inc. slope mine. Situate on the north dip, #8 Vein, Mount Carmel Township, Northumberland County, Pennsylvania.
 Alfred B. Riedel, P.E. November 11, 1987
 Scale 1" = 100'

Alfred B. Riedel