



A.B. Riedel

VENTILATION SYMBOLS			
(F) = Main Fan	⊠ = Air Bridge		
(O) = Auxiliary Fan	⌞ = Regulator		
➡ = Air Flow - Intake	⌞ = Man Door		
➡ = Air Flow - Exhaust	V = Velocity, fpm		
+ = Permanent Stopping	Q = Quantity, cfm		
+ = Temporary Stopping	WG = Water Gauge		

MINE MAP

Showing the location and extent of development (from Operator) of the Buck Mountain Coal Company's slope mine. Situate on the north dip of the Buck Mountain vein, Butler Twp., Schuylkill County, Pa.

A.B. Riedel, P.E. May 12, 1986
Scale 1"=100'

36-05116