



- ESCAPING VENTILATION SYMBOLS
- | | |
|---------------------------|---------------------|
| (F) = Main Fan | (A) = Air Bridge |
| (O) = Auxiliary Fan | (R) = Regulator |
| (G) = Air Flow - Intake | (M) = Man Door |
| (E) = Air Flow - Exhaust | (V) = Velocity, fpm |
| (+) = Permanent Stopping | (Q) = Quantity, cfm |
| (-) = Temporary Stopping | (WG) = Water Gauge |

MINE MAP

Showing the location and extent of development of the Buck Mountain #2 Coal Company slope mine. Situate on the north dip Buck Mountain vein, Tremont Township, Schuylkill County, Pennsylvania.

A. B. Riedel, P.E. July 17, 1986
Scale 1" = 100'

A. B. Riedel
1175