



VENTILATION SYMBOLS			
(F) = Main Fan	⌘ = Air Bridge		
(O) = Auxiliary Fan	⌘ = Regulator		
→ = Air Flow - Intake	⌘ = Man Door		
→ = Air Flow - Exhaust	V = Velocity, fpm		
+ = Permanent Stopping	Q = Quantity, cfm		
+ = Temporary Stopping	WG = Water Gauge		

MINE MAP
Showing the location and extent of development of the New Lincoln Coal Company slope mine. Situate on the East dip L.V. #1 Vein, Tremont Twp., Schuylkill County, Pa.
A.B. Riedel, P.E. Jan. 14, 1986
Scale 1"= 100'