


MINE MAP  
of the  
New Lincoln Coal Company Workings  
situate  
Tremont & Frailey Townships, Schuylkill County.



| VENTILATION SYMBOLS |                            |
|---------------------|----------------------------|
| (F)                 | = Main Fan                 |
| (A)                 | = Auxiliary Fan            |
| →                   | = Air Flow - Intake        |
| ←                   | = Air Flow - Exhaust       |
| ⊥                   | = Permanent Stopping       |
| ⊥                   | = Temporary Stopping       |
| ⊥                   | = Air Bridge               |
| R                   | = Regulator                |
| ⊥                   | = Man Door                 |
| V                   | = Velocity, fpm            |
| Q                   | = Quantity, cfm            |
| WG                  | = Water Gauge              |
| (E)                 | = Escapeway                |
| BEP                 | = Bleeder Evaluation Point |



*april B. Lead*