



VENTILATION SYMBOLS	
(F) = Main Fan	AB = Air Bridge
AMT = Air Mover with Tubing	R = Regulator
→ = Air Flow - Intake	MD = Man Door
↗ = Air Flow - Exhaust	V = Velocity, fpm
+ = Permanent Stopping	Q = Quantity, cfm
• = Temporary Stopping	WG = Water Gauge
Active Working delineated in yellow	

MINE MAP
Showing the location and extent of development of the New Lincoln Coal Company slope mine. Situate on the East dip L.V. #1 Vein, Tremont Twp., Schuylkill County, Pa.
A.B. Riedel, P.E. Jan. 14, 1986
Scale 1"= 100'