



VENTILATION SYMBOLS			
(F) = Main Fan	□ = Air Bridge		
(A) = Auxiliary Fan	⌋ = Regulator		
→ = Air Flow - Intake	⌋ = Man Door		
→ = Air Flow - Exhaust	V = Velocity, fpm		
+ = Permanent Stopping	Q = Quantity, cfm		
+ = Temporary Stopping	WG = Water Gauge		

MINE MAP

Showing the location and extent of development of the Little Buck Mountain Coal Co. slope mine. Situate on the North dip Little Buck Mountain Vein, Tremont Township, Schuylkill County, PA. 36-07547

A.B. Riedel, P.E. November 16, 1989  
Scale 1"=100'