

- Ventilation Symbols
- ① Main Fan
 - ② Auxiliary Fan
 - Intake Air
 - Return Air
 - Stoppings
 - Air Bridge
 - R Regulator
 - MD Man Door
 - Q Quantity of Air
 - WG Water Gauge
 - ③ Escapeway
 - SEP Blower Evaluation Point
 - Bobbing
 - Active workings (yellow)

MINE OPERATOR'S CERTIFICATION

I depose and say that the mine ventilation information shown on this map meets the requirements of 30 CFR Part 75.372 and was prepared by me or under my direction for which I accept full responsibility.

James J. [Signature]
Mine Foreman

SURVEYOR'S CERTIFICATION

I hereby certify that to the best of my knowledge that the areas that I have surveyed are true and correct as to the requirements of 30 CFR Part 75.200. All other information shown has been derived from the best available information but can not be field checked. Therefore, surveyor makes no certification to their accuracy.

David J. [Signature]
Surveyor

Revised January 5, 1995 after receiving additional mine map information from MSHA.

MINE MAP
of the
JACK COAL COMPANY MINE WORKINGS
Hegins Township, Schuylkill County

Scale: 1 inch = 100 feet