



VENTILATION SYMBOLS

- Ⓕ = Main Fan
- Ⓐ = Auxiliary Fan
- = Air Flow - Intake
- ⇝ = Air Flow - Exhaust
- |— = Permanent Stopping
- - -| - - - = Temporary Stopping
- ⊠ = Air Bridge
- R = Regulator
- ⌋ = Man Door
- V = Velocity, fpm
- Q = Quantity, cfm
- WG = Water Gauge
- Ⓔ = Escapeway
- BEP = Bleeder Evaluation Point

MINE MAP
of the
S & M Coal Company Slope Mine
Wicomico Township, Dauphin County

100 50 0 50 100
Scale 1 inch = 100 feet

Alfred B. Riser