



WOODWARD

GODWIN

W LOVELAND

Dirty Coal

No 1 Slope

No 1 East

No 1 1/2 East

No 2 East

No 2 1/2 West

No 3 West

No 3 East

Do not mine over this line

Do not mine over this line

WOODWARD COLLY
CORPORATION
SECRETARY
DEC. 8 1959