



#17 BAST COLLIERY
 CROSS SECTION ON LINE OF COAL HOISTING SHAFT
 SCALE: 100 FT. PER INCH F. F. WEISER, CIV. ENGR. ASHLAND, MARCH 24-1910

W|0 3 7 -|0 1 0| $\frac{1}{3}$ -| $\frac{1}{100}$ |30|

Fig. D.C.M. above.
 1000' = 1" = 100'
 100' = 1" = 10'
 10' = 1" = 1'
 1' = 1" = 1"

W|0 3 7 -|0 1 0| $\frac{2}{3}$ -| $\frac{1}{100}$ |30|