


⊕ INDICATES WHERE KENNEDY WAS WORKING, LOADING ROCK, WHEN HE "FELL DEAD."

● INDICATES WHERE TWO "BUDDIES" WERE WORKING.



THE VESTA COAL CO.
CALIFORNIA, PA.
MINE Nº4 - SCENE OF DEATH OF
ROBT. KENNEDY SEPT. 21-1936

SEPT. 29-1936	D-749
SCALE 1"=10'	