

STRAIGHTIFF.

STRAIGHTIFF.

J. P. NORTH.

J. S. STRAIGHTIFF.
73A. 113P. COAL.

HUFF LANDS.

WHITEHEAD LANDS.

F. P. NORTH.
69A. 233P.

HENRY FALKNER.

W. D. VACHOB
Worked Out.

A. J. SHEESLEY.
104A. 116.3P. COAL.

GEO. NOERR.

HENRY ERNST
117 A. FEE.

M. HUMMELL.
54A. 96P. FEE.
SURFACE SOLD TO
GEO. THOMPSON.

KESSLER.
SOLD TO
MRS. WRIGHT.
68A. 78P. UT.

OLDN^o 10.
West Eureka 10

DDH #56
No Coal.

DDH #58
No Coal.

DDH #55
No Coal.

DDH #66
No Coal.

DDH #69
No Coal.

DDH #54
No Coal.

DDH #65
No Coal.

DDH #53
No Coal.

DDH #64
No Coal.

No Coal.



N

B - W. C. M. Co.

No 1
J. G. HENRY
FEE 86 A.

THIS PART OF MAP
COPIED FROM OLD MAP OF
B-W.C.M. Co.

SCALE: 1" = 400'

CLEARFIELD, PA. OFFICE OF E. W. HESS,
SEPT. 10, 1920. ENGINEER.

504A

DuBois Office - File 504A