



Wedges were not placed on top of cut.

Rock fall from "A" to "B" crushing victim to death.

No. 15 Room
T-17 Hdg.

Cross-cut

To outside

D-C-42

4215
015