



LEGEND

- MINE BOUNDARY
- SURFACE SUPPORT AREA
- ACTIVE BOREHOLE
- SEALED BOREHOLE
- SEALED SHAFT
- ▲ 001 DISCHARGE LOCATION
- STREAM MONITORING POINT

CONSOLIDATION COAL COMPANY
 NORTHERN WEST VIRGINIA OPERATIONS
 P.O. BOX 100, OSAGE, WV 26543

HUMPHREY MINE NO. 7
 PERMIT NO. 30841302

LOCATION MAP
 EXHIBIT 6.2 & 8.0

SCALE: 1" = 2000'
 MARCH 2008

PERRY & WHITELEY TOWNSHIP - GREENE COUNTY, PENNSYLVANIA
 OSAGE, & BLACKSVILLE WY. & GARARDS FORT & OAK FOREST PA. U.S. COORDINATE QUADRANGLES
 7.5 MINUTE SERIES - 20' CONTOUR INTERVAL

JUL 17 2008
 DEPT. OF ENVIRONMENTAL PROTECTION
 ASSISTANT ATTORNEY GENERAL

I, THE UNDERSIGNED, HEREBY CERTIFY THAT THIS MAP IS ACCURATE AND TRUE TO THE BEST OF MY KNOWLEDGE AND BELIEF ALL INFORMATION CONTAINED HEREIN IS TRUE AND CORRECT.

VAN W. PITMAN

STATE OF WEST VIRGINIA
 COUNTY OF MONONGALIA

TAKEN, SUBSCRIBED AND SWORN TO BEFORE ME THIS _____ DAY OF _____ 2008

MY COMMISSION EXPIRES: DECEMBER 7, 2002

NOTARY PUBLIC: *Sheirl Fletcher*
 SHEIRL FLETCHER