

IF ISOLATED SECTIONS AS THIS BARRIER INDICATES SHOULD BECOME EFFECTIVE PAYMENT FOR COAL REMAINING TO BE PAID FOR

PROJECTED 20 BARRIERS SHOULD BE ELIMINATED

10-8-58
STARTING SECTION
STILL WITH 1910
EVIDENCE OF BUT SEE BOP
LATER
THAT WAS DONE IN THE
4 CROSSCUTS AND 27
R-1 IS OK BUT
L-1 IS HOLLOWED
NEARLY HOLLOWED OUT
TO SHOW SET THIS BEING
MINED

SUMP
PILLARS TO
BE MINED

PROJECTED BARRIER
IF NOT MINED SHOULD BE PAID FOR
M. WEIMER
SUMP

PILLAR TO BE MINED ON FINAL RETREAT
POOR ROOF
AREA

SEE MEMO OF 4-23-58

BLEEDER SEE MEMO OF 4-23-58

RECORDED
INDEXED
MAY 15 1958
U.S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
WASHINGTON, D.C.

MAP SHOWING
PROPERTY AND MINING OPERATIONS
OF THE
IMPERIAL KEYSTONE COAL CO.
SITUATE IN
CHERRYHILL, RAYNE & GREEN TOWNSHIPS, INDIANA CO., PA.
SCALE: 1" = 100'
JUNE 2, 1958
RECD 8-27-58
PETTERMAN ENGINEERING CO.

J. WIDDOWSON

W. GIBSON

JOHN MCGUIRE

J.S. ROWE

ISAAC MCGUIRE

BARNETT

D. OBER

P. HOUCK

N. WIDDOWSON

D. HOUCK