

1000'

D. H. PASSMORE
FEE

CLUSTER SNYDER
LEASED

W. F. PATTON
FEE

JOHN SNYDER
LEASED

OUTCROP

JAMES & ISAAC REA
COAL IN FEE

MARGARET E. HOFFMAN
FEE

JOHN M. REA

IRVIN, NORRIS & JOHNSON
FEE

MAP

OF

CARNWATH COAL CO.

SHOWING DEPLETION OF No 1 MINE

KNOX TOWNSHIP

CLEARFIELD COUNTY, PA.

SCALE 1" = 400'

CLEARFIELD, PA.,
JUNE 12, 1920

OFFICE E. W. HESS,
ENGINEER

MRS. ELLEN ROOT
FEE

POTTS RUN LAND CO.
LEASED

BLOOM & BELL

BERNARD FARRAN

JOHN E. WITHEROW

#464
6-22-20
cc.